

# COMPANY STANDARD

## HS Marston Aerospace Limited

a UTC Aerospace Systems company  
Wolverhampton, England  
TEL: +44 (0) 1902 572777  
FAX: +44 (0) 1902 572888



Document Number: ME899	Sheet 1 of 14	Date: 19/12/2016	Issue: 34
------------------------	---------------	------------------	-----------

<b>TITLE: HS MARSTON AEROSPACE LIMITED REPAIR AND OVERHAUL CAPABILITY LIST</b>
--

### FOREWORD AND SCOPE

This Company Standard lists the Repair and Overhaul Capabilities of the HS Marston Aerospace Limited.

This procedure is to be read in conjunction with:-

ME898 EASA/FAA145 Maintenance Organisation Exposition.

Note : Amendments to this Capability List shall require Approval by the CAA if the amendment involves the introduction of new, unique or novel technologies, or any addition other than 'C' Ratings, shown on the applicable Form 3 and components detailed within the MOE Component Maintenance Scope of Work.

As a Company Standard this document will not normally be divulged to third parties, but where this requirement does occur it must be carried out on an official basis and with the permission of the Company Quality Manager

<b>UK EXPORT CONTROL</b> - check box that applies and add classification number					
UK MILITARY		UK/EU DUAL USE		NOT UK/EU EXPORT CONTROLLED	X
UK ML RATING		DUAL USE RATING			
This document contains technical data subject to the export control laws of the United Kingdom Government. Transfer or release of this data by any means to a foreign interest, whether made within the United Kingdom or abroad, without an applicable export licence or other authorisation from the United Kingdom Government is prohibited.		This document contains technical data subject to UK/EU Dual Use export control. Transfer or release of this data by any means to a foreign interest outside of the EU without an applicable export licence or other authorisation from the United Kingdom Government is prohibited.		This document is not subject to UK / EU Export Control	
<b>US EXPORT CONTROL</b> - check box that applies and add classification number					
US ITAR		US EAR		NO CONTROLLED US ORIGIN DATA	X
US ML CLASSIFICATION		ECCN			
This document contains technical data subject to the export control laws of the United States, specifically including the Arms Export Control Act, 22 U.S.C. 2751 et. seq., and the International Traffic in Arms Regulations (ITAR), 22 C.F.R. part 120 et. seq. Transfer, retransfer, or disclosure of this data by any means to a non-U.S. person (individual or company), whether in the United States or abroad, without any required export license or other approval from the U.S. Government is prohibited.		This document contains technology subject to the export control laws of the United States, specifically including the Export Administration Regulations (EAR), 15 C.F.R. Part 730 et. seq. Transfer, retransfer, or disclosure of this data by any means to a non-U.S. person (individual or company), whether in the United States or abroad, without any required export license or other approval from the U.S. Government is prohibited, including without limitation any diversion to a military end user or use in a military end use application.		US recipients are responsible for determining the applicable US jurisdiction/classification before any re-export or re-transfer from the US.	
COMPILED			APPROVED BY OWNER / DEPARTMENT		
NAME	DEPT.	NAME	DEPT.		
I.Bullock	MRO	I.Asgar	Quality		
SIGNATURE			SIGNATURE		
COPYRIGHT © HS MARSTON AEROSPACE LIMITED This document contains confidential information which is the property of HS Marston Aerospace Limited. The document must NOT be copied nor its contents communicated to any person or company without authorization in writing from HS Marston Aerospace Limited. Any authorized recipients may only use this document for the purpose for which it has been supplied. Copyright, patent, design right or any other intellectual property right relating to any features disclosed in the document vests exclusively with HS Marston Aerospace Limited. The trademark Marston is used under license from IMI Marston Limited.					

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

Document Number: ME899	Sheet 2 of 14	Date: 19/12/2016	Issue: 34
------------------------	---------------	------------------	-----------

## CHANGE HISTORY

Date	Revision from	Revision to	Description of change
12/10/2015	31	32	Addition of part number 7010124H01 – Heat Exchanger condenser paragraph 2.201. For purpose of embodiment of service bulletin SB 7010124-21-1
03/11/2015	32	33	Ref. to IMI Marston deleted from page 1 Ref to ME1013 deleted from page 1 Export Control boxes corrected on page 1 Page numbers corrected Obsolete parts deleted.
19/12/2016	33	34	The wording in “Forward and scope” on page 1 amended. Page 14 – Section 3.1: 3059766-02 added Page 13 D2552-700B,D2552-800B,D2552-800B-01, H2144 Series, H2149 Series, H2179 Series added.

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

Document Number: ME899

Sheet 3 of 14

Date: 19/12/2016

Issue: 34

## INDEX

<u>Section</u>	<u>Description</u>	<u>Sheet No</u>
	Foreword and Scope	1
	Change History	2
	Index	3
1	Introduction	4
2	Capability Schedule for Heat Transfer Group (HTG)	5-13
3	Capability Schedule for Fluids Management Group (FMG)	14

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

Document Number: ME899

Sheet 4 of 14

Date: 19/12/2016

Issue: 34

## 1 INTRODUCTION

HS Marston Aerospace Limited have the capability to Repair and Overhaul equipment listed in Sections 2 and 3 of this Capability List.

The scope of repairs and the procedure for their accomplishment are described in the Component Maintenance Manuals (CMM) or Approved Repair Schemes issued by the original manufacturers.

A Traveller Card and Shop Order Operation Notes are written for each item of equipment and references are made to the CMM and/or Approved Repair Scheme for the repair procedures.

When goods are released to the Customer, the CMM number and/or Approved Repair Scheme number and issue are referenced on the release documentation.

Any `additions` or `deletions` of part numbers to this capability list shall be by completion of Form HSM/Q067 only. Submittal of this form to the CAA for approval is only required for the criteria defined under the heading Forward and Scope of this document on page 1

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

Document Number: ME899	Sheet 5 of 14	Date: 19/12/2016	Issue: 34
------------------------	---------------	------------------	-----------

## 2 CAPABILITY SCHEDULE – Heat Transfer Group (HT)

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.1	Hamilton Sundstrand	719235-4	21-51-02	B747	EASA/FAA
2.2	Hamilton Sundstrand	719235-5	21-51-02	B747	EASA/FAA
2.3	Hamilton Sundstrand	719235-6	21-51-02	B747	EASA/FAA
2.4	Hamilton Sundstrand	719235-7	21-51-02	B747	EASA/FAA
2.5	Hamilton Sundstrand	719235-8	21-51-02	B747	EASA/FAA
2.6	Hamilton Sundstrand	719235-9	21-51-02	B747	EASA/FAA
2.7	Hamilton Sundstrand	719235-4	ME242/19235	B747	EASA/FAA
2.8	Hamilton Sundstrand	719235-5	ME242/19235	B747	EASA/FAA
2.9	Hamilton Sundstrand	719235-6	ME242/19235	B747	EASA/FAA
2.10	Hamilton Sundstrand	719235-7	ME242/19235	B747	EASA/FAA
2.11	Hamilton Sundstrand	719235-8	ME242/19235	B747	EASA/FAA
2.12	Hamilton Sundstrand	719235-9	ME242/19235	B747	EASA/FAA
2.19	Ametek Hughes Treitler	12325-000	79-21-02	Honeywell Alf 502	EASA/FAA
2.20	Ametek Hughes Treitler	13325-000	79-21-02	Honeywell Alf 502	EASA/FAA
2.21	Ametek Hughes Treitler	2-303-491-01	79-21-02		EASA/FAA
2.22	Ametek Hughes Treitler	2-303-491-02	79-21-02		EASA/FAA
2.23	Ametek Hughes Treitler	11698-000	24-11-01	PW4000	EASA/FAA
2.24	Ametek Hughes Treitler	12698-000	24-11-01	PW4000	EASA/FAA
2.25	Ametek Hughes Treitler	11622-000	79-21-20	EASA/FAA	
2.26	Ametek Hughes Treitler	12622-000	79-21-20		EASA/FAA
	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.27	Ametek Hughes Treitler	13622-000	79-21-20		EASA/FAA

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

<b>Document Number:</b> ME899	<b>Sheet 6 of 14</b>	<b>Date:</b> 19/12/2016	<b>Issue:</b> 34
-------------------------------	----------------------	-------------------------	------------------

2.28	Ametek Hughes Treitler	15622-000	79-21-20		EASA/FAA
2.29	HS Marston Aerospace	D1150-10A	24-23-01	BAE146	EASA/FAA
2.30	HS Marston Aerospace	D1151-10A	29-20-01	BAE146	EASA/FAA
2.31	HS Marston Aerospace	D1443-100A	79-21-11	CASA CN-235	EASA/FAA
2.32	HS Marston Aerospace	D1688-200A	79-21-31	P180	EASA/FAA
2.33	HS Marston Aerospace	D1719-200A	73-10-01	PT6B	EASA/FAA
2.34	HS Marston Aerospace	D1719-300A	63-10-01	PT6B	EASA/FAA
2.35	HS Marston Aerospace	D1719-400A	63-10-01	PT6B	EASA/FAA
2.36	HS Marston Aerospace	D1719-500A	63-10-01	PT6B	EASA/FAA
2.37	HS Marston Aerospace	D1834-10A	79-21-21	CASA C-212	EASA/FAA
2.38	HS Marston Aerospace	D1834-100A	79-21-21	CASA C-212	EASA/FAA
2.39	HS Marston Aerospace	D1979-200A	49-90-01	B747	EASA/FAA
2.40	HS Marston Aerospace	D2310-10A	79-21-41	AW109	EASA/FAA
2.41	HS Marston Aerospace	D2346-10A	49-91-01	Dart	EASA/FAA
2.42	HS Marston Aerospace	D291-2A	28-4-1	Dart	EASA/FAA
2.43	HS Marston Aerospace	D291-8A	28-5-1	Dart	EASA/FAA
2.44	HS Marston Aerospace	D291-52A	28-5-1	Dart	EASA/FAA
2.45	HS Marston Aerospace	D291-53°	28-6-1	Dart	EASA/FAA
2.46	HS Marston Aerospace	D291-85°	28-3-1	Dart	EASA/FAA
2.47	HS Marston Aerospace	D3292-1600°	24-10-53	B747	EASA/FAA
2.48	HS Marston Aerospace	D3292-1700°	24-10-53	B747	EASA/FAA
2.49	HS Marston Aerospace	D3292-1800°	24-10-53	B747	EASA/FAA
	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.50	HS Marston Aerospace	D3292-3000A	75-21-01	B747	EASA/FAA I
2.51	HS Marston Aerospace	D3292-4000A	75-21-01	B747	EASA/FAA
2.52	HS Marston Aerospace	D3439-1300A	79-20-05	B747	EASA/FAA
2.53	HS Marston Aerospace	D2552-600B-01	73-10-05	Cessna	EASA/FAA

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

<b>Document Number:</b> ME899	<b>Sheet</b> 7 <b>of</b> 14	<b>Date:</b> 19/12/2016	<b>Issue:</b> 34
-------------------------------	-----------------------------	-------------------------	------------------

2.54	HS Marston Aerospace	D2552-600B-02	73-10-05	Cessna	EASA/FAA
2.55	HS Marston Aerospace	D1508-120A	73-11-12	CASA CN-235	EASA/FAA
2.56	HS Marston Aerospace	D1573-10A	73-15-05	SF340	EASA/FAA
2.57	HS Marston Aerospace	D1569-64A	73-11-3	R.R.Spey	EASA/FAA
2.58	HS Marston Aerospace	D1569-80A	73-11-3	R.R.Spey	EASA/FAA
2.59	HS Marston Aerospace	D1569-120A	73-11-3	R.R.Spey	EASA/FAA
2.60	HS Marston Aerospace	D1876-1000A	75-22-41	A319/320/321	EASA/FAA
2.61	HS Marston Aerospace	D2041-1000A	36-10-05	B747	EASA/FAA
2.62	HS Marston Aerospace	D2045-300A	49-90-02	B747	EASA/FAA
2.63	HS Marston Aerospace	D2228-250A	73-10-1	Tyne	EASA/FAA
2.64	HS Marston Aerospace	D2397-10A	79-10-01		EASA/FAA
2.65	HS Marston Aerospace	D3047-270A	36-10-2	BAC 1-11	EASA/FAA
2.66	HS Marston Aerospace	D3047-271A	36-10-2	BAC 1-11	EASA/FAA
2.67	HS Marston Aerospace	D3047-280A	36-10-2	BAC 1-11	EASA/FAA
2.68	HS Marston Aerospace	D3047-281A	36-10-2	BAC 1-11	EASA/FAA
2.69	HS Marston Aerospace	D3047-700A	36-10-2	BAC 1-11	EASA/FAA
2.70	HS Marston Aerospace	D3047-701A	36-10-2	BAC 1-11	EASA/FAA
2.71	HS Marston Aerospace	D3117-1A	36-10-3	BAC 1-11	EASA/FAA
2.72	HS Marston Aerospace	D3117-2A	36-10-3	BAC 1-11	EASA/FAA
	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.73	HS Marston Aerospace	D3117-601A	36-10-3	BAC 1-11	EASA/FAA
2.74	HS Marston Aerospace	D3117-602A	36-10-3	BAC 1-11	EASA/FAA
2.75	HS Marston Aerospace	D3117-651A	36-10-3	BAC 1-11	EASA/FAA
2.76	HS Marston Aerospace	D3117-652A	36-10-3	BAC 1-11	EASA/FAA
2.77	HS Marston Aerospace	D3117-691A	36-10-3	BAC 1-11	EASA/FAA
2.78	HS Marston Aerospace	D3117-692A	36-10-3	BAC 1-11	EASA/FAA
2.79	HS Marston Aerospace	D2022-100A	ME242	A319/320/321	EASA/FAA
2.80	HS Marston Aerospace	D2022-140A	ME242	A319/320/321	EASA/FAA

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

<b>Document Number:</b> ME899	<b>Sheet</b> 8 <b>of</b> 14	<b>Date:</b> 19/12/2016	<b>Issue:</b> 34
-------------------------------	-----------------------------	-------------------------	------------------

2.81	HS Marston Aerospace	D2024-100A	ME242	A319/320/321	EASA/FAA
2.82	HS Marston Aerospace	D2024-140A	ME242	A319/320/321	EASA/FAA
2.83	Secan	11-82941-M2	TS2024-5		EASA/FAA
2.84	Secan	11-8291-M3	TS2022-5		EASA/FAA
2.85	Sundstrand	723324(2-303-254-01)	79-21-01	Honeywell	EASA/FAA
2.86	Sundstrand	723324A(2-0303-254-02)	79-21-01	Honeywell	EASA/FAA
2.87	Sundstrand	723324B(2-303-254-03)	79-21-01	Honeywell	EASA/FAA
2.88	Sundstrand	723324C(2-303-254-05)	79-21-01	Honeywell	EASA/FAA
2.89	Sundstrand	723324D(2-303-254-06)	79-21-01	Honeywell	EASA/FAA
2.90	Ametek Hughes Treitler	14844-000	24-21-42	A319/320/321	EASA/FAA
2.91	Ametek Hughes Treitler	15844-000	24-21-42	A319/320/321	EASA/FAA
2.92	Ametek Hughes Treitler	16844-000	24-21-42	A319/320/321	EASA/FAA
2.93	Ametek Hughes Treitler	60141-000	24-21-32		EASA/FAA
2.94	Ametek Hughes Treitler	60010-000	24-10-14		EASA/FAA
2.95	Ametek Hughes Treitler	70010-000	24-10-14		EASA/FAA
	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.96	Ametek Hughes Treitler	80010-000	24-10-14		EASA/FAA
2.97	Hamilton Sundstrand	810210-1	21-72-02	B777	EASA/FAA
2.98	Hamilton Sundstrand	810210-2	21-72-02	B777	EASA/FAA
2.99	Hamilton Sundstrand	810208-1	21-52-02	B777	EASA/FAA
2.100	Hamilton Sundstrand	810208-2	21-52-02	B777	EASA/FAA
2.101	Hamilton Sundstrand	810208-4	21-52-02	B777	EASA/FAA
2.102	Hamilton Sundstrand	810208-5	21-52-02	B777	EASA/FAA
2.104	Hamilton Sundstrand	810208-6	21-52-02	B777	EASA/FAA
2.105	Hamilton Sundstrand	810208-7	21-52-02	B777	EASA/FAA
2.106	Hamilton Sundstrand	810208-9	21-52-02	B777	EASA/FAA



# HS Marston Aerospace Limited

a UTC Aerospace Systems company

<b>Document Number:</b> ME899	<b>Sheet</b> 9 <b>of</b> 14	<b>Date:</b> 19/12/2016	<b>Issue:</b> 34
-------------------------------	-----------------------------	-------------------------	------------------

2.107	Hamilton Sundstrand	810208-102	21-52-02	B777	EASA/FAA
2.108	Hamilton Sundstrand	810208-104	21-52-02	B777	EASA/FAA
2.109	Hamilton Sundstrand	810208-105	21-52-02	B777	EASA/FAA
2.110	Hamilton Sundstrand	810208-114	21-52-02	B777	EASA/FAA
2.111	Hamilton Sundstrand	810208-115	21-52-02	B777	EASA/FAA
2.112	Hamilton Sundstrand	810208-117	21-52-02	B777	EASA/FAA
2.113	Ametek Hughes Treitler	11553-000	11553-00		EASA/FAA
2.114	Ametek Hughes Treitler	12553-000	11553-00		EASA/FAA
2.115	Hamilton Sundstrand	815950-1	39-12-17		EASA/FAA
2.116	HS Marston Aerospace	163521538	FRS 6887	B747	EASA/FAA
2.117	HS Marston Aerospace	D2887-615A	79-21-61	Dash 8 Q400	EASA/FAA
2.118	HS Marston Aerospace	D2887-715A	79-21-61	Dash 8 Q400	EASA/FAA
2.119	HS Marston Aerospace	D2887-815A	79-21-61	Dash 8 Q400	EASA/FAA
	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.120	HS Marston Aerospace	D2967-100A	73-10-15	PT 6	EASA/FAA
2.121	HS Marston Aerospace	D2967-200A	73-10-15	PT 6	EASA/FAA
2.122	HS Marston Aerospace	D6031-200A	73-10-20	PW308	EASA/FAA
2.123	HS Marston Aerospace	D6031-300A	73-10-20	PW308	EASA/FAA
2.124	HS Marston Aerospace	D6031-400A	73-10-20	PW308	EASA/FAA
2.125	HS Marston Aerospace	D6031-500A	73-10-20	PW308	EASA/FAA
2.126	HS Marston Aerospace	D6031-600A	73-10-20	PW308	EASA/FAA
2.127	HS Marston Aerospace	D6031-700A	73-10-20	PW308	EASA/FAA
2.128	HS Marston Aerospace	D2351-100A	73-10-10	PW206	EASA/FAA
2.129	HS Marston Aerospace	D2351-200A	73-10-10	PW206	EASA/FAA
2.130	Hamilton Sundstrand	820905-1	21-53-04	Dash 8 Q400	EASA/FAA
2.131	Hamilton Sundstrand	820905-2	21-53-04	Dash 8 Q400	EASA/FAA

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

Document Number: ME899	Sheet 10 of 14	Date: 19/12/2016	Issue: 34
------------------------	----------------	------------------	-----------

2.132	Hamilton Sundstrand	820905-3	21-53-04	Dash 8 Q400	EASA/FAA
2.133	Hamilton Sundstrand	4950242	49-91-03	A319/320/321	EASA/FAA
2.134	Hamilton Sundstrand	4950862	49-91-03	A319/320/321	EASA/FAA
2.135	Hamilton Sundstrand	4950882	49-91-03	A319/320/321	EASA/FAA
2.136	Hamilton Sundstrand	4951093	49-91-03	A319/320/321	EASA/FAA
2.137	Hamilton Sundstrand	M4950242	49-91-03	A319/320/321	EASA/FAA
2.138	Hamilton Sundstrand	M4950862	49-91-03	A319/320/321	EASA/FAA
2.139	Hamilton Sundstrand	M4951093	49-91-03	A319/320/321	EASA/FAA
2.140	HS Marston Aerospace	D6397-10A	36-30-00	Embraer 170/190	EASA/FAA
2.141	HS Marston Aerospace	HEA3610E161-501	30-11-04	Embraer 170/190	EASA/FAA
2.142	HS Marston Aerospace	HEA3610E163-501	30-11-04	Embraer 170/190	EASA/FAA
	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.143	HS Marston Aerospace	HEA3610E181-503	30-11-04	Embraer 170/190	EASA/FAA
2.144	HS Marston Aerospace	HEA3610E183-503	30-11-04	Embraer 170/190	EASA/FAA
2.145	HS Marston Aerospace	HEA3610E186-501		Embraer 170/190	EASA/FAA
2.146	HS Marston Aerospace	HEA3610E187-501		Embraer 170/190	EASA/FAA
2.147	HS Marston Aerospace	HEA3610E180-501		Embraer 170/190	EASA/FAA
2.148	HS Marston Aerospace	HEA3610E182-501		Embraer 170/190	EASA/FAA
2.149	HS Marston Aerospace	D6557-10A	79-21-42	A380	EASA/FAA
2.150	HS Marston Aerospace	D6557-100A	79-21-42	A380	EASA/FAA
2.151	HS Marston Aerospace	D6557-200A	79-21-42	A380	EASA/FAA
2.152	HS Marston Aerospace	D6557-300A	79-21-42	A380	EASA/FAA
2.153	HS Marston Aerospace	D6557-400A	79-21-42	A380	EASA/FAA
2.154	HS Marston Aerospace	D6514-10A	24-21-41	A380	EASA/FAA
2.155	HS Marston Aerospace	D6514-100A	24-21-41	A380	EASA/FAA
2.156	HS Marston Aerospace	D6514-200A	24-21-41	A380	EASA/FAA

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

<b>Document Number:</b> ME899	<b>Sheet</b> 11 <b>of</b> 14	<b>Date:</b> 19/12/2016	<b>Issue:</b> 34
-------------------------------	------------------------------	-------------------------	------------------

2.157	HS Marston Aerospace	D6514-300A	24-21-41	A380	EASA/FAA
2.158	HS Marston Aerospace	D6514-400A	24-21-41	A380	EASA/FAA
2.159	Sumitomo	50026001-1	79-21-42		EASA/FAA
2.160	Sumitomo	OA2730-001	79-21-42		EASA/FAA
2.161	Sumitomo	50034001-1	79-28-03		EASA/FAA
2.162	Sumitomo	OA3150-001	79-28-03		EASA/FAA
2.163	Sumitomo	OF25-001	79-21-43		EASA/FAA
2.164	Sumitomo	OF25-101	79-21-43		EASA/FAA
2.165	Sumitomo	OF25-201	79-21-43		EASA/FAA
	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.166	Sumitomo	OF25-301	79-21-43		EASA/FAA
2.167	Sumitomo	OF25-401	79-21-43		EASA/FAA
2.168	Sumitomo	OF32-001	79-21-43		EASA/FAA
2.169	Sumitomo	OF32-101	79-21-43		EASA/FAA
2.170	Sumitomo	OF33-001	79-21-43		EASA/FAA
2.171	Sumitomo	55022001-1	79-21-43		EASA/FAA
2.172	Sumitomo	55022001-11	79-21-43		EASA/FAA
2.173	Sumitomo	55025001-01	79-21-43		EASA/FAA
2.174	Sumitomo	55030001-11	79-21-43		EASA/FAA
2.175	HS Marston Aerospace Ltd	D1876-5000A	75-22-41	A319/320/321	EASA/FAA
2.176	HS Marston Aerospace Ltd	D2887-355C	79-21-61	Dash 8 Q400	EASA/FAA
2.177	HS Marston Aerospace Ltd	D6599-1000A (157666-1)	21-50-01	A380	EASA/FAA
2.178	HS Marston Aerospace Ltd	7010106H02 (D7026-300A)	21-73-06	B787	EASA/FAA
2.179	HS Marston Aerospace Ltd	7011041H01 (H2013-10)	21-52-78	B787	EASA/FAA
2.180	HS Marston Aerospace Ltd	7011043H01	21-52-78	B787	EASA/FAA

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

Document Number: ME899	Sheet 12 of 14	Date: 19/12/2016	Issue: 34
------------------------	----------------	------------------	-----------

(H2014-10)

2.181	Hamilton Sundstrand	753355-4	21-51-63	DHC8 100,200,300	EASA/FAA
2.182	Hamilton Sundstrand	753355-8	21-51-63	DHC8 100,200,300	EASA/FAA
2.183	Hamilton Sundstrand	753355-9	21-51-63	DHC8 100,200,300	EASA/FAA
2.184	Hamilton Sundstrand	778683-2	21-51-50	DHC8 100,200,300	EASA/FAA
2.185	Hamilton Sundstrand	778683-3	21-51-50	DHC8 100,200,300	EASA/FAA
2.186	Hamilton Sundstrand	778683-4	21-51-50	DHC8 100,200,300	EASA/FAA

	<u>Original Manufacturer</u>	<u>Part No</u>	<u>Repair Scheme</u>	<u>Platform</u>	<u>Release</u>
2.187	Hamilton Sundstrand	778683-5	21-51-50	DHC8 100,200,300	EASA/FAA
2.188	Sumitomo	50069001-1	79-21-42		EASA/FAA
2.189	Ametek Hughes Treitler	2-303-491-02	ORI NO. P34650		EASA/FAA
2.190	HS Marston Aerospace Ltd	D2967-400A	73-10-15	PT 6	EASA/FAA
2.191	HS Marston Aerospace Ltd	163521545	FRS6887	B747	EASA/FAA
2.192	Hamilton Sundstrand	820905-5	21-53-04	Dash 8 Q400	EASA/FAA
2.193	HS Marston Aerospace Ltd	7011041H02	21-52-78	B787	EASA/FAA
2.194	HS Marston Aerospace Ltd	7011043H2	21-52-78	B 787	EASA/FAA
2.195	Sumitomo	CH1716-0307	LRS8761	EASA/FAA	
2.196	Sumitomo	CH1558A0092	LRS8780	EASA/FAA	
2.197	Sumitomo	CH1795A0060	LRS8781	EASA/FAA	
2.198	Sumitomo	CH251371.CSC	LRS8749 &	LRS8755	EASA/FAA
2.199	Hamilton Sundstrand	816630-1	21-51-69	Embraer 145	EASA/FAA
2.200	Hamilton Sundstrand	816630-2	21-51-69	Embraer 145	EASA/FAA
2.201	Hamilton Sundstrand	7010124H01	SB7010124-21-1	B787	EASA/FAA
2.202	HS Marston Aerospace	D2552-700B	73-10-05	Cessna	EASA/FAA
2.203	HS Marston Aerospace	D2552-800B	73-10-05	Cessna	EASA/FAA
2.204	HS Marston Aerospace	D2552-800B-01	73-10-05	Cessna	EASA/FAA

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

<b>Document Number:</b> ME899	<b>Sheet</b> 13 <b>of</b> 14	<b>Date:</b> 19/12/2016	<b>Issue:</b> 34
-------------------------------	------------------------------	-------------------------	------------------

2.205	HS Marston Aerospace	1022848 (H2144 Series)	79-21-66	A320 Neo	EASA/FAA
2.206	HS Marston Aerospace	1021569 (H2149 Series)	24-22-47	A320 Neo	EASA/FAA
2.207	HS Marston Aerospace	1023264 (H2179 Series)	24-22-46	A320 Neo	EASA/FAA

# HS Marston Aerospace Limited

a UTC Aerospace Systems company

Document Number: ME899

Sheet 14 of 14

Date: 19/12/2016

Issue: 34

## 3 CAPABILITY SCHEDULE – Fluid Management Group (FM)

### Harness

814300027  
814300028  
814300048  
814300007  
6583-3  
9176  
9177-2  
9256  
9276  
9277  
82402046

3.1	<u>HSM Part No.</u>	<u>Customer Part No.</u>	<u>Description</u>	<u>Repair Scheme</u>	
	043524583-02	(3044609-02)	Fuel Manifold	CMM73-11-40	PD1016
	043524583-01	(3044610-02)	Fuel Manifold	CMM73-11-40	PD1016
	033524591	(3053186-01)	Fuel Manifold	CMM73-11-40	PD1016
	063524592-02	(30C2847-01)	Fuel Manifold	CMM73-11-40	PD1016
	063524592-01	(30C2848-01)	Fuel Manifold	CMM73-11-40	PD1016
	043524597	(30J2433-01)	Fuel Manifold	CMM73-11-40	PD1016
	043524596	(30C2849-01A)	Fuel Manifold	CMM73-11-40	PD1016
	063524593	(31J2248-01)	Fuel Manifold	CMM73-11-40	PD1016
	043524557	(31J2248-01)	Fuel Manifold	CMM73-11-40	PD1016
	033527419	(3059766-01)	Fuel Manifold	CMM73-11-40	PD1016
		(3059766-02)	Fuel Manifold	CMM73-11-40	PD1016
	043527420-01	(3059764-01)	Fuel Manifold	CMM73-11-40	PD1016
	043527420-02	(3059765-01)	Fuel Manifold	CMM73-11-40	PD1016
	063524592-01	(30C2848-01)	Fuel Manifold	CMM73-11-40	PD1016
	043527417	(3059905-01)	Fuel Manifold	CMM73-11-40	PD1016
		(01R3053186-01)	Fuel Manifold	CMM73-11-40	PD1016
		(01R3053842-01)	Fuel Manifold	CMM73-11-40	PD1016
	033527204	(4951707)	Fuel Manifold		PD1016
	033527205	(4951708)	Fuel Manifold		PD1016
	033526003	(WE3883962-1)	Fuel Manifold		PD1016
	063524585	(3048387-01)	Fuel Manifold		PD1016

**NOTE: FAA Release will only be raised by Fluids Management Group for product which is eligible for 'N' registered aircraft.**